
Drinking Water Inspection Checklist

AZ04-	04035	Name RIM TRAIL DWID
Done	Features File review	
/	Monitoring	Complete Violations NHatt (Rund)
	1.4	Violations 10174444 (Jeans V)
	Schedule Insp	ection Date/Time JQJUN1
_	Inspection Rig	hts
2	Signage	
/	Well (quantity)	2
		Casing Cover Slab Vent Sample tap
/		Slab Gond
	4	Vent Sample tap
		Secure
		Log Za
	Components	Secure
/		Secure Vegetation
/		Maintenance
V	Storage (quant	
		Vent screen Overflow Jaku 1-2
1.		Footing
7		Hatch Secure
/		Tank condition
1	Cross Connection Potential	
		Backflow Prevention
~	Sampling	1.20
		Chlorine residual 1.39
	ICF	Other
1	Draft report/vio	lation
	Photos Other	
Notes:		

Rim Trail DWID PWS #AZ0404035 Photos taken 20JUN11





1) Well 1 (55-645071) back-up





3 & 4) Well 3 (55-645070) pump house and insulated well head.



5 & 6) Interior pump house well 3.

Rim Trail DWID PWS #AZ0404035 Photos taken 20JUN11



7 & 8) Surface water source.



9) Siphon box.



10) Siphon pump.